

https://fwupdate.ruuvi.com/v1.15.0

En | Fi

Ruuvi Gateway A405

Software Update

Please wait. Do not power off the Ruuvi Gateway during the update!

Downloading the main processor software

Downloading the user interface

Downloading the coprocessor software

Finishing the setup

En | Fi

Ruuvi Gateway A405

Software Update

Failure:

Failed to update OTA

Please reboot the device. Locate the pinhole button under the power socket and press the button briefly using a paperclip.

Ruuvi Gateway A405

Software Update

Failure:

Failed to updo

Please reboot the button bri

Oh no! Connection to the Ruuvi Gateway is lost.

Please reconnect to the Wi-Fi hotspot. If the hotspot is not active, start it again. Locate the pinhole button under the power socket and press the button briefly using a paperclip.

t and press